
## The 9500 Series Family


STARLINE WINDOWS


Series 9502 & 9503


Thermally Broken Aluminum Outswing Balcony Door



Quality, Comfort & Peace of Mind









THIS DETAIL IS A SUGGESTED METHOD OF INSTALLATION AND DOES NOT REPRESENT A DETAIL THAT IS SUITABLE FOR A SPECIFIC PROJECT. TO CONFIRM PROJECT SPECIFIC DETAILS, PLEASE CHECK WITH YOUR WATERPROOFING/BUILDING ENVELOPE CONSULTANT.

DRAWINGS ARE SUBJECT TO CHANGE WITHOUT NOTICE

 AUTHOR:
 DATE:
 DWG NO:

 S.R.R.
 FEB. 2018
 9502 - DWG 3





## SERIES 9502 - 90 DEGREE SEISMIC CORNER COUPLER

THIS DETAIL IS A SUGGESTED METHOD OF INSTALLATION AND DOES NOT REPRESENT A DETAIL THAT IS SUITABLE FOR A SPECIFIC PROJECT. TO CONFIRM PROJECT SPECIFIC DETAILS, PLEASE CHECK WITH YOUR WATERPROOFING/BUILDING ENVELOPE CONSULTANT.

DRAWINGS ARE SUBJECT TO CHANGE WITHOUT NOTICE

 AUTHOR:
 DATE:
 DWG NO:

 S.R.R.
 FEB. 2018
 9502 - DWG 4

